

Laboratorios Zurita, Quito (Ecuador)

Case Study



record D STA 20 double leaf sliding door in full glass version with tempered safety glass
RIC 290 AC combined sensor (detection and safety) and BDE-D electronic control unit

(in total 6 sliding doors)

Laboratorios Zurita, Quito (Ecuador)

Case Study



Laboratorios Zurita, Quito (Ecuador)

Case Study



Laboratorios Zurita, Quito (Ecuador)

Case Study

